

NATIONAL PROGRAM FOR INSPECTION OF NON-FEDERAL DAMS
MINNEAPOLIS DAM (NH 001) (U) CORPS OF ENGINEERS WALTHAM
MA NEW ENGLAND DIV SEP 78


1/4

F/G 13/13

NL

END

FILS(f)



MICROCOPY RESOLUTION TEST CHART
NATIONAL BUREAU OF STANDARDS-1963 A

AD-A155 098

DTIC ACCESSION NUMBER

II

LEVEL

PHOTOGRAPH THIS SHEET

MINNEWAWA DAM

N.H. 00104

NHWRB-151.06

INVENTORY

DOCUMENT IDENTIFICATION

SEPT 1978

This document has been approved
for public release and sale; its
distribution is unlimited.

DISTRIBUTION STATEMENT

ACCESSION FOR

NTIS GRA&I ☒

DTIC TAB ☐

UNANNOUNCED ☐

JUSTIFICATION

BY

DISTRIBUTION /

AVAILABILITY CODES

DIST

AVAIL AND/OR SPECIAL

A-1

DISTRIBUTION STAMP

Copy available to DTIC does not
permit fully legible reproduction



DTIC
ELECTE
JUN 12 1985
S E D

DATE ACCESSIONED

DATE RETURNED

85 06 12 017

DATE RECEIVED IN DTIC

REGISTERED OR CERTIFIED NO.

PHOTOGRAPH THIS SHEET AND RETURN TO DTIC-DDAC

AD-A155 098

CONNECTICUT, RIVER BASIN
MARLBOROUGH, NEW HAMPSHIRE

MINNEWAWA DAM

N.H. 00104

NHWRB-151.06

PHASE I INSPECTION REPORT
NATIONAL DAM INSPECTION PROGRAM



DEPARTMENT OF THE ARMY
NEW ENGLAND DIVISION, CORPS OF ENGINEERS
WALTHAM, MASS.

SEPTEMBER 1978

85 06 12 017

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

A155 11/8

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER NH 00104	2. GOVT ACCESSION NO.	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) Minnewawa Dam		5. TYPE OF REPORT & PERIOD COVERED INSPECTION REPORT
NATIONAL PROGRAM FOR INSPECTION OF NON-FEDERAL DAMS		6. PERFORMING ORG. REPORT NUMBER
7. AUTHOR(s) U.S. ARMY CORPS OF ENGINEERS NEW ENGLAND DIVISION		8. CONTRACT OR GRANT NUMBER(s)
9. PERFORMING ORGANIZATION NAME AND ADDRESS		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
11. CONTROLLING OFFICE NAME AND ADDRESS DEPT. OF THE ARMY, CORPS OF ENGINEERS NEW ENGLAND DIVISION, NEDED 424 TRAPELO ROAD, WALTHAM, MA. 02254		12. REPORT DATE September 1978
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office)		13. NUMBER OF PAGES 58
		15. SECURITY CLASS. (of this report) UNCLASSIFIED
		15a. DECLASSIFICATION/DOWNGRADING SCHEDULE
16. DISTRIBUTION STATEMENT (of this Report) APPROVAL FOR PUBLIC RELEASE: DISTRIBUTION UNLIMITED		
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)		
18. SUPPLEMENTARY NOTES Cover program reads: Phase I Inspection Report, National Dam Inspection Program; however, the official title of the program is: National Program for Inspection of Non-Federal Dams; use cover date for date of report.		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) DAMS, INSPECTION, DAM SAFETY, Connecticut River Basin Marlborough, New Hampshire Minnewawa Brook		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) Based on the visual inspection, available records and past performance, the dam is considered to be in fair condition. The dam is believed to be safe under normal operating conditions. Based on size and hazard classifications in accordance with Corps guidelines, the test flood is the PMF. In addition to long term recommendations, there are several remedial measures which should be implemented immediately.		

DISCLAIMER NOTICE

**THIS DOCUMENT IS BEST QUALITY
PRACTICABLE. THE COPY FURNISHED
TO DTIC CONTAINED A SIGNIFICANT
NUMBER OF PAGES WHICH DO NOT
REPRODUCE LEGIBLY.**

MINNEWAWA DAM

N.H. 00104

CONNECTICUT, RIVER BASIN

MARLBOROUGH, NEW HAMPSHIRE

PHASE I INSPECTION REPORT

NATIONAL DAM INSPECTION PROGRAM

PHASE I REPORT
NATIONAL DAM INSPECTION PROGRAM

Identification No.:	-	N.H. 00104
Name of Dam:	-	Minnewawa Dam
Town:	-	Marlborough
County and State:	-	Cheshire County, New Hampshire
Stream:	-	Minnewawa Brook
Date of Inspection:	-	13 Jan 78, 7 Jun 78

BRIEF ASSESSMENT

Based on the visual inspection, available records and past performance, the Minnewawa Dam is considered to be in fair condition. The dam is believed to be safe under normal operating conditions. Its serviceability under the test flood load and ice forces is unknown. These peak loading conditions should be more fully investigated.

Based on size and hazard classifications in accordance with Corps guidelines, the test flood is the Probably Maximum Flood. A PMF outflow of 19,000 cfs (826 csm) would overtop the dam by 7.2 feet. The spillway will pass 1710 cfs, or about 9 percent of the PMF outflow. A cursory analysis was made to assess the downstream impact of a sudden failure. With the reservoir at top of dam, it is estimated that a 17-foot surge would result just downstream of the structure over the water level that existed just before failure. Due to the extreme steepness of the channel slope and banks between the dam and the first grouping of homes, 0.7 mile downstream, little attenuation of the flood wave could be expected and a high hazard to loss of life would result.

Due to the potential for overtopping and the lack of formal stability analyses, it is recommended in Section 7 of this report that the owner engage the services of a qualified consultant to evaluate the stability of the concrete arch. Further, a more detailed investigation should be made of the hydraulic and hydrologic aspects of the dam.

In addition to the long term recommendations, there are several remedial measures which should be implemented immediately.

1. Periodic Inspections of Minnewawa Dam by the owner should be established.
2. A formal warning program should be developed and implemented, along with a plan for monitoring the structure during periods of unusually high flow.
3. There is a considerable amount of brush in the spillway approach channel, which should be controlled.

4. Both the sluice gate and penstock gates are inoperative. The penstock trash rack is clogged with debris. The sluice appears susceptible to blockages. Both should be inspected and cleaned periodically.

William H. Rodger
WILLIAM H. RODGER P.E.
Massachusetts Reg. #29048

This Phase I Inspection Report on Minnewawa Dam has been reviewed by the undersigned Review Board members. In our opinion, the reported findings, conclusions, and recommendations are consistent with the Recommended Guidelines for Safety Inspection of Dams, and with good engineering judgment and practice, and is hereby submitted for approval.



CHARLES G. TIERSCH, Chairman
Chief, Foundation and Materials Branch
Engineering Division




FRED J. RAVENS, Jr., Member
Chief, Design Branch
Engineering Division



SAUL COOPER, Member
Chief, Water Control Branch
Engineering Division

APPROVAL RECOMMENDED:



JOE B. FRYAR
Chief, Engineering Division

PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D.C. 20314. The purpose of a Phase I Investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation, and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. In cases where the reservoir was lowered or drained prior to inspection, such action, while improving the stability and safety of the dam, removes the normal load on the structure and may obscure certain conditions which might otherwise be detectable if inspected under the normal operating environment of the structure.

It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through continued care and inspection can there be any chance that unsafe conditions be detected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established Guidelines, the Spillway Test flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. Because of the magnitude and rarity of such a storm event, a finding that a spillway will not pass the test flood should not be interpreted as necessarily posing a highly inadequate condition. The test flood provides a measure of relative spillway capacity and serves as an aide in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.

TABLE OF CONTENTS

<u>Section</u>	<u>Page</u>
Transmittal Letter	
Brief Assessment	
Review Board Page	
Preface	i
Table of Contents	ii,iii,iv
Overview Photos	v,
Location Map	vi

REPORT

1. PROJECT INFORMATION

1.1 General	1-1
a. Authority	
b. Purpose	

1.2 Description of Project	1-1
a. Location	
b. Description of Dam and Appurtenances	
c. Size Classification	
d. Hazard Classification	
e. Ownership	
f. Operator	
g. Purpose of Dam	
h. Design and Construction History	
i. Normal Operational Procedures	

1.3 Pertinent Data	1-2
a. Drainage Area	
b. Discharge at Damsite	
c. Elevations	
d. Reservoir	
e. Storage	
f. Reservoir Surface	
g. Dam	
h. Spillway	
i. Regulating Outlets	

<u>SECTION</u>	<u>Page</u>
2. ENGINEERING DATA	
2.1 Design	2-1
2.2 Construction	2-1
2.3 Operation	2-1
2.4 Evaluation	2-1
3. VISUAL INSPECTION	
3.1 Findings	3-1
a. General	
b. Dam	
c. Appurtenant Structures	
d. Reservoir Area	
e. Downstream Channel	
3.2 Evaluation	3-1
4. OPERATIONAL PROCEDURES	
4.1 Procedures	4-1
4.2 Maintenance of Dam	4-1
4.3 Maintenance of Operating Facilities	4-1
4.4 Description of any Warning System in Effect	4-1
4.5 Evaluation	4-1
5. HYDRAULIC/HYDROLOGIC	
5.1 Evaluation of Features	5-1
a. Design Data	
b. Experience Data	
c. Visual Observations	
d. Overtopping Potential	

SECTION

Page

6. STRUCTURAL STABILITY

6.1 Evaluation of Structural Stability

6-1

- a. Visual Observations
- b. Design and Construction Data
- c. Operating Records
- d. Post Construction Changes
- e. Seismic Stability

7. ASSESSMENT, RECOMMENDATIONS AND REMEDIAL MEASURES

7.1 Dam Assessment

7-1

- a. Condition
- b. Adequacy of Information
- c. Urgency
- d. Need for Additional Investigation

7.2 Recommendations

7-1

7.3 Remedial Measures

7-1

- a. Alternatives
- b. Operation and Maintenance Procedures

APPENDIXES

APPENDIX A - PERIODIC INSPECTION CHECKLIST

A-1

APPENDIX B - DAM PLAN AND PAST INSPECTION REPORTS

B-1

APPENDIX C - PHOTOGRAPHS

C-1

APPENDIX D - HYDROLOGIC AND HYDRAULIC COMPUTATIONS

D-1

APPENDIX E - INFORMATION AS CONTAINED IN THE NATIONAL
INVENTORY OF DAMS

E-1

APPENDIX A

(3) There is a considerable amount of brush in the spillway approach channel, which should be controlled.

(4) Both the sluice gate and penstock gates are inoperative. The penstock trash rack is clogged with debris. The sluice appears susceptible to blockages. Both should be inspected and cleaned periodically.

SECTION 7 - ASSESSMENT, RECOMMENDATIONS AND REMEDIAL MEASURES

7.1 Dam Assessment.

a. Condition. Based on the visual inspection, available records and past performance, the Minnewawa Dam is considered to be in fair condition.

b. Adequacy of Information. Information gathered during the search of the project files is considered to be adequate to make a valid assessment of the pertinent features of Minnewawa Dam.

c. Urgency. Recommendations and remedial measures made by this report should be accomplished within 12 months after the receipt of this Phase I report by the owner.

d. Need for Additional Investigation. As previously stated, Minnewawa Dam is considered to be in fair condition, but further study by a qualified consultant is recommended to cover the subjects listed in Para. 7.2 below.

7.2 Recommendations.

a. Since the spillway can pass about 9 percent of the test flood without overtopping the dam, a qualified consultant should be engaged to assess hydrological conditions and develop plans for any modification necessary to avoid overtopping.

Analyses of the structural stability of the concrete arch should be included in the consultants scope of work. The response of the arch to ice loads and effects of temperature changes should be investigated by the consultant.

7.3 Remedial Measures.

a. Alternatives. Not applicable - Alternative solutions to improve inadequate spillway capacity are beyond the scope of this report.

b. Operating and Maintenance Procedures. Operating procedures employed at Minnewawa Dam are inadequate. Therefore, the following O&M procedures are recommended.

(1) A biennial periodic technical inspection program for Minnewawa Dam should be established.

(2) A formal warning program should be developed and implemented, along with a plan for monitoring the structure during periods of unusually high flow.

c. Operating Records. There are no records which indicate a stability problem since the dam was built in 1923. There have been several major events during the life of the structure. Therefore, the dam's performance with respect to stability has been adequate to date.

d. Post Construction Changes. There is no data indicating any modifications have been made to the dam since construction was completed. The inspection revealed the spillway and portions of the main arch have been treated with gunite.

e. Seismic Stability. The dam is located in Seismic Zone No. 2 and in accordance with recommended Phase I guidelines does not warrant seismic analysis.

SECTION 6 - STRUCTURAL STABILITY

6.1 Evaluation of Structural Stability.

a. Visual Observations. No evidence was observed indicating structural instability of the concrete arch or spillway at this time. However, several conditions which could affect the overall stability of the dam were noted.

(1) There is a significant amount of efflorescence on the downstream face of the dam. These deposits are caused by leakage through the dam.

(2) The extent of major cracks and spalled areas of concrete should be more fully investigated. This information will yield a better check on the present stability of the concrete arch.

(3) Reinforcing steel was exposed on the upstream face of the dam. The size and grade of steel is unknown. The steel is continuous thru the horizontal construction joints and the vertical construction joints. Spacing of reinforcing is estimated to be 12" on center in both directions.

These conditions could have an effect upon structural stability in the future and should be further investigated by a qualified consultant.

b. Design and Construction Data. Pertinent design and construction data for Minnewawa Dam is described in Section 1.2.g. - Design and Construction and SECTION 2 - ENGINEERING DATA.

The original stability stress analysis for the concrete arch is available. The maximum compressive stresses in the dam are relatively small compared to the estimated ultimate compressive strength of the concrete mix used during construction. The analysis of the arch is consistent with accepted engineering practices. No stability or stress analysis was performed for ice loads or the effects of temperature changes. In addition to the computed behavior, the past performance of the dam must be considered. There has been no major failure of the structure during its 55-year existence. The evaluation of present stability must include an accurate determination of the dam's existing condition. There are areas of significant cracking and spalled concrete with exposed reinforcing steel which cause a decrease in the effective sections of the arch. This reduction causes a subsequent increase in stresses within the arch.

Based on the visual inspection, available records and past performance, Minnewawa Dam is believed to be structurally stable during normal operating conditions. Stability during the projected test flood and ice forces cannot be determined by visual observations. Therefore, these peak loading conditions should be more fully investigated.

SECTION 5 - HYDRAULIC/HYDROLOGIC

5.1 Evaluation of Features.

a. Design Data. A search of Public Service Company of New Hampshire and New Hampshire Water Resources Board files revealed no detailed hydraulic or hydrologic design data.

b. Experience Data. There is no experience data available. It was stated in section 1.3 that the maximum flood of record for the site is estimated to be in excess of 150 csm. No damages to the structure occurred during this event.

c. Visual Observations. The shore of the lake is totally undeveloped. Inundation of this area would occur during the test flood. However, no damage to life or property could occur in the reservoir area.

There is no streambank development for a distance of about 0.7 mile downstream. Beginning at this point, however, there are several homes constructed on or near the streambank. These would be lost or heavily damaged in the event of any type of dam failure. About 1.6 miles downstream of the dam, Minnewawa Brook meets N.H. Route 101 and the village of Marlborough. Due to the steepness of the channel and banks between the dam and this area, a breach could produce considerable disruption of travel and probable loss of life.

d. Overtopping Potential. Based on U.S. Geological Survey Water Supply Paper 1887, "Maximum Floodflows in the Conterminous United States", the Probable Maximum Flood (PMF) for Minnewawa Brook is estimated to be 31,000 cfs (1,348 csm). However, 1.8 square miles, or 8 percent of the upstream drainage area is occupied by lakes and ponds which would tend to reduce peak flows.

The Corps of Engineers' MacDowell Dam is located on Nubanusit Brook, 12 miles east of Minnewawa Dam. The watersheds are adjacent, and contain similar amounts of storage. The Probable Maximum Flood used in designing MacDowell Dam was 36,300 cfs (825 csm). Based on the similar watershed characteristics, 19,000 cfs, or 826 csm was selected as the PMF for Minnewawa Brook.

Based on the size classification (INTERMEDIATE) and the hazard potential (HIGH), the full PMF was selected as the test flood. A discharge of 19,000 cfs would result in a peak pool elevation of 1,080.2 feet msl, or 7.2 feet over the top of dam. With both gates open, this value would be lowered about 0.2 feet.

SECTION 4 - OPERATIONAL PROCEDURES

4.1 Procedures. As previously discussed both outlets are left open at all times, and the project is not operated for flood control purposes. During the summer, the reservoir is essentially empty.

4.2 Maintenance of Dam. There is no formal annual maintenance program for Minnewawa. Necessary minor repairs to the dam have not been made. Funds for major repairs must be appropriated by the Public Service Co. of New Hampshire.

4.3 Maintenance of Operating Facilities. Not applicable for Minnewawa Dam.

4.4 Description of any Warning System in effect. There is no warning system during flood periods.

4.5 Evaluation. Periodic inspections of Minnewawa Dam by engineers from the Public Service Co. of New Hampshire must be established. Minor deficiencies can be eliminated by annually maintaining the structure. Major repairs are the responsibility of Public Service.

A formal warning program should be developed and implemented, along with a plan for monitoring the structure during periods of unusually high flow.

SECTION 3 - VISUAL INSPECTION

3.1 Findings.

a. General. The Phase I inspection of the dam and Minnewawa Brook was performed on 13 January 1978. The area adjacent to the dam was covered with 18 inches of snow. The pool was below the spillway crest. The concrete spillway and arch were reinspected 7 June 1978. The pool was completely drawn down. This allowed access to the downstream and upstream faces of the dam under dry conditions. A copy of the visual inspection report is included in Appendix A. Photographs contained in Appendix C have been keyed to the inspection check list.

b. Dam. The dam is considered to be in fair condition. There was no evidence of vertical or horizontal misalignment detected in the dam. However, the dam does require maintenance and several concrete repairs.

(1) The concrete arch has a significant amount of efflorescence on the downstream face. Many cracks, which appear to be shrinkage cracks, were noted. No leakage was observed during the inspection. It should be noted the pool was low during the winter inspection and there was no water impounded during the June inspection.

(2) There were spalled areas of concrete on both the upstream and downstream faces of the arch. Reinforcing steel was exposed on the upstream face.

c. Appurtenant Structures. Not applicable to Minnewawa Dam.

d. Reservoir Area. The shore of the lake is totally undeveloped. Inundation of this area would occur during the test flood. However, no damage to life or property could occur in the reservoir area.

e. Downstream Channel. There is no streambank development for a distance of about 0.7 mile downstream. Beginning at this point, however, there are several homes constructed on or near the streambank. These would be lost or heavily damaged in the event of any type of dam failure. About 1.6 miles downstream of the dam, Minnewawa Brook meets N.H. Route 101 and the village of Marlborough. Due to the steepness of the channel and banks between the dam and this area, a breach could produce considerable disruption of travel and probable loss of life.

3.2 Evaluation. As stated previously, the condition of Minnewawa Dam is considered to be fair. No major problems associated with either the serviceability or operation of the dam were discovered. There are, however, several areas which will require periodic maintenance and concrete repairs to ensure continued serviceability.

SECTION 2- ENGINEERING DATA

2.1 Design. There was design data available for Minnewawa. Letters pertaining to the original design and specifications were obtained. The available design data included some stability computations.

2.2 Construction. Construction records for the original project were obtained. These records give a general overall picture of the structure and its pertinent features. Sketches showing the elevation and section of the dam and pertinent design and construction records are included in Appendix B.

2.3 Operation. Information pertaining to the operation and operational procedures was not available.

2.4 Evaluation. There is a limited amount of engineering data available for this project. The general features of the existing structures, sections and elevations are detailed. A limited amount of engineering design criteria was gained from this information.

Data for the report was made available by the combined cooperative efforts of the New Hampshire Water Resources Board and the Public Service Company of New Hampshire.

d. Reservoir.

Length of Pool - varies around 0.2 mile (+ 0.1 mi.)

e. Storage (acre-feet).

Normal Pool - varies (see capacity curve Appendix D)

Spillway Crest - 140 (approx.)

Top Dam - 175 (approx.)

f. Reservoir Surface (acres).

Pool surface varies with pool fluctuations.

g. Dam.

Type	Concrete Arch
Length	Approx. 200 feet
Height	Varies, 60' Max.
Top Width	4'-0"

Side Slopes

Concrete Arch

(a) Vertical Upstream Face

(b) The downstream face is vertical for the top 10.00 feet and has a 1.5 horizontal on 10 vertical batter below this point.

h. Spillway. The side-channel spillway consists of a 45-foot ogee weir. A 1.5-foot pier results in an effective spillway length of 43.5 feet. The crest is at elevation 1068. There are no spillway gates.

There is a shallow spillway approach channel, now overgrown with brush. Flows from the spillway pass through a narrow rock cut, then plunge about 60 feet to the main river channel, just downstream of the dam. Photographs of these features are included in Appendix C.

i. Regulating Outlets. There are two regulating outlets: a 4-foot circular penstock with invert at about elevation 1049, and a 2-foot circular sluice with invert at about elevation 1020. The penstock formerly extended 6,000 feet downstream to a power station, but has since been removed, and now has a free outfall into the dam's tailwater. With the pool at spillway crest, the total outlet capacity is about 340 cfs (15csm), which is considered adequate.

The penstock gate, which has been removed, was hand-operated from atop the dam. The sluice gate is hand-operated from a platform at the toe of the dam. The condition of the gate machinery is questionable and believed inoperative. Pictures are located in Appendix C.

f. Operator.

Public Service Co. of New Hampshire
Hampshire Plaza
Manchester, N.H.
Tel: (Area Code 603) 669-4000

g. Purpose of Dam. The initial purpose was to provide a pool for hydroelectric power generation. At present, the dam is not utilized for any purpose.

h. Design and Construction History. Minnewawa Dam was completed in November, 1923. It was designed and constructed by L.H. Shattuck, Inc., Engineers-Contractors, 208 Granite Street, Manchester, New Hampshire for the Ashuelot Gas and Electric Company, Keene, New Hampshire (now Public Service Company of New Hampshire). Sketches pertaining to the pertinent features of Minnewawa were obtained from the Water Resources Board. Correspondence pertaining to foundation conditions, design parameters and a set of construction photographs were also obtained. Essential information pertaining to the design and construction of the dam is contained in Appendix B.

i. Normal Operation Procedures. Both gates in the structure are left open at all times, and the pool elevation fluctuates depending on runoff conditions in the watershed. At the time of the inspection, the pool was at about elevation 1056 feet, msl. The project is not operated for flood control purposes. During the June inspection, the pool was at the sluice invert El. 1020 (+).

1.3 PERTINENT DATA.

a. Drainage Area at Damsite. 23 square miles.

b. Discharge at Damsite. There are no discharge records available for the site. The largest known flood in this region occurred in September, 1938. Examination of U. S. Geological Survey records for other streams in the area indicate Minnewawa Brook sustained flows in excess of 150 cubic feet per second per square mile (csm).

Flows may be passed through the 2-foot sluice, through the 4-foot penstock, over the 43.5 foot spillway, or over the 200-foot crest of the dam. With the pool at elevation 1073 (top of dam), the spillway capacity is 1650 cfs (72 csm). A rating curve for the spillway and top of dam is located in Appendix D.

c. Elevations (feet, msl).

Top of Dam - 1073
Spillway Crest - 1068
Normal Pool - fluctuates (essentially empty during the summer)
Penstock Invert - 1049 (scaled from photos)
Sluice Invert - 1020 (scaled from photos)
Streambed at Dam Centerline - 1012 (approx.)

PHASE I INSPECTION REPORT

MINNEWAWA DAM, NEW HAMPSHIRE 00104

SECTION 1 - PROJECT INFORMATION

1.1 GENERAL

a. Authority. Public Law 92-367, August 8, 1972, authorized the Secretary of the Army, through the Corps of Engineers, to initiate a national program of dam inspection throughout the United States. The New England Division of the Corps of Engineers has been assigned the responsibility of supervising the inspection of dams within the New England Region.

b. Purpose.

(1) Perform technical inspection and evaluation of non-Federal dams to identify conditions which threaten the public safety and thus permit correction in a timely manner by non-Federal interest.

(2) Encourage and assist the States to initiate quickly effective dam inspection programs for non-Federal dams.

(3) To update, verify and complete the National Inventory of Dams.

1.2 DESCRIPTION OF PROJECT.

a. Location. The dam is located on the western end of the impoundment of Minnewawa Brook in the Town of Marlborough, New Hampshire, approximately 1.6 miles upstream of the village of Marlborough.


b. Description of Dam and Appurtenances. The Minnewawa Dam is a constant radius concrete arch dam. The structure has two distinct features. The arch section is 200 feet long and has a top elevation of 1073.0 (msl). This arch is keyed into ledge. The concrete spillway, which is approximately 43.5 feet long, has a crest elevation of 1068.0 (msl). The spillway is also founded on ledge.

c. Size Classification. Minnewawa is an intermediate dam, based on height.

d. Hazard Classification. The structure is classified as a high hazard potential. (See Section 3.1.e).

e. Ownership. The dam is owned by the Public Service Company of New Hampshire.

MONADNOCK, N.H. QUADRANGLE



MINNEWAWA DAM



DOWNSTREAM FACE



UPSTREAM FACE

APPENDIX A - MINNEWAWA DAM

PHASE I

VISUAL INSPECTION

PARTY ORGANIZATION

PROJECT Minnewawa Dam DATE 7 June 1978
 LOCATION Marlboro, New Hampshire TIME 10:00
 STREAM Minnewawa Brook WEATHER Sunny
 Inventory No. N.H. #00104 W.S. FEET. - U.S. - DN.S. -

PARTY:

- | | |
|-------------------------|-----------|
| 1. <u>W. Rodger</u> | 6. _____ |
| 2. <u>G. A. Laraway</u> | 7. _____ |
| 3. <u>J. McElroy</u> | 8. _____ |
| 4. _____ | 9. _____ |
| 5. _____ | 10. _____ |

PROJECT FEATURE	INSPECTED BY	REMARKS
1. <u>Sluice Outlet (Fig. 13 & 15)</u>	<u>Laraway</u>	<u>Some debris</u>
2. <u>Penstock Outlet (Fig. 13 & 14)</u>	<u>Laraway</u>	<u>Some debris</u>
3. <u>Spillway (Fig. 16 & 17)</u>	<u>Laraway</u>	<u>Inadequate</u>
4. <u>Concrete Arch (Fig. 6 & 7)</u>	<u>McElroy, Rodger</u>	<u>See Check List</u>
5. _____	_____	_____
6. _____	_____	_____
7. _____	_____	_____
8. _____	_____	_____
9. _____	_____	_____
10. _____	_____	_____

- NOTE: 1. Portions of the structure appear to have been repaired with a gunite coat. No record of this treatment was found.
 2. (Fig. No.) refers to photographs contained in Appendix C.

PHASE I

VISUAL INSPECTION CHECK LIST

PROJECT	<u>Minnewawa Dam</u>	DATE	<u>7 June 1978</u>
PROJECT FEATURE	<u>Conc. Arch</u>	NAME	<u>Rodger</u>
DISCIPLINE	<u>Structure, & Concrete</u>	NAME	<u>McElroy</u>

AREA EVALUATED	COMMENTS
<u>DAM</u> (Fig. 3 thru 10)	
Crest Elevation	1073.0 msl
Current Pool Elevation	1021.0 msl
Maximum Impoundment to Date	Unknown
Surface Cracks	Many surface cracks with efflorescence downstream.
Pavement Condition	N/A
Movement or Settlement of Crest	None Observed.
Lateral Movement	Appears Good.
Vertical Alignment	Appears Good.
Horizontal Alignment	Appears Good.
Condition at Abutment and at Concrete Structures	Good.
Indications of Movement of Structural Items on Slopes	N/A
Trespassing on Slopes	N/A
Sloughing or Erosion of Slopes or Abutments	N/A
Rock Slope Protection - Riprap Failures	N/A
Unusual Movement or Cracking at or near Toes	None
Unusual Downstream Seepage	None
Piping or Boils	N/A
Foundation Drainage Features	None
Toe Drains	None
Instrumentation System	None

PHASE I

VISUAL INSPECT OR CHECK LIST

PROJECT	<u>Minnewawa Dam</u>	DATE	<u>7 June 1978</u>
PROJECT FEATURE	<u>Outlet</u>	NAME	<u>Inspection Team</u>
DISCIPLINE	<u>-</u>	NAME	<u>-</u>

AREA EVALUATED	COMMENTS
<u>OUTLET WORKS</u> (Fig. 13 thru 15)	
a. Concrete and Structural	
General Condition	Fair
Condition of Joints	Good
Spalling	Several large spalls
Visible Reinforcing	Yes, upstream face of dam
Rusting or Staining of Concrete	Yes
Any Seepage or Efflorescence	Yes, downstream face
Joint Alignment	Good
Unusual Seepage or Leaks in Gate Chamber	N/A reservoir down
Cracks	Numerous surface cracks
Rusting or Corrosion of Steel	Both exposed re-steel & trash rack bars
b. Mechanical and Electrical	
Air Vents	None
Float Wells	Abandoned
Crane Hoist	None
Elevator	None
Hydraulic System	None
Service Gates	Inoperative
Emergency Gates	None
Lightning Protection System	None
Emergency Power System	None
Wiring and Lighting System in Gate Chamber	None

PHASE I

VISUAL INSPECTION CHECK SHEET

PROJECT Minnewawa Dam

DATE 7 June 1978

PROJECT FEATURE Outlet

NAME Inspection Team

DISCIPLINE -

NAME -

AREA EVALUATED	COMMENTS
<u>OUTLET STRUCTURE</u>	(Fig. 9, 11 & 12)
General Condition of Concrete	Fair
Rust or Staining	Some
Spalling	Yes
Erosion or Cavitation	Yes
Visible Reinforcing	Yes
Any Seepage or Efflorescence	Some
Condition at Joints	Good
Drain Holes	N/A
Channel	N/A
Loose Rock or Trees Overhanging Channel	None
Condition of Discharge Channel	Natural channel - good

PHASE I

VISUAL INSPECTION CHECK LIST

PROJECT	<u>Minnewawa Dam</u>	DATE	<u>7 June 1978</u>
PROJECT FEATURE	<u>Spillway</u>	NAME	<u>Inspection Team</u>
DISCIPLINE	<u>-</u>	NAME	<u>-</u>

AREA EVALUATED	COMMENTS
<u>SPILLWAY, APPROACH AND/OR DISCHARGE CHANNELS</u>	
a. Approach Channel	(Fig. 1)
General Condition	Some brush
Loose Rock Overhanging Channel	None
Trees Overhanging Channel	None
b. Training Walls	
General Condition of Concrete	Good
Rust or Staining	None
Spalling	None
Any Visible Reinforcing	No
Any Seepage or Efflorescence	No
Drain Holes	None
c. Discharge Channel	(Fig. 2, 17)
General Condition	Fair
Loose Rock Overhanging Channel	None
Trees Overhanging Channel	None loose (see photos)
Floor of Channel	Rock
Other Obstructions	None

APPENDIX B

APPENDIX B - CONTENTS

- | | |
|--|--------------------|
| 1. Project Description | dated 1923 |
| 2. Letter from L.H.Shattuck, Inc. | dated 18 June 1923 |
| 3. Computations | dated 25 June 1923 |
| 4. New Hampshire Water Control Commission
data, (3 pages) | dated 30 Jan 1939 |
| 5. Inspection report | dated 7 Sept 1923 |
| 6. Test report (Sand) | dated 20 Sept 1923 |
| 7. Test report (Cement) | dated 13 Sept 1923 |
| 8. Inspection Report | dated 19 Sept 1923 |
| 9. Letter from L.H. Shattuck, Inc.
re: expansion of construction joints | dated 4 Oct 1923 |
| 10. Field sketches, showing concrete placement
sequence | |
| 11. Inspector's Report | dated 6 Nov 1923 |
| 12. Inspector's Report | dated 4 Dec 1923 |
| 13. Inspection Report | dated 19 June 1930 |
| 14. Inspection Report | dated 27 Aug 1976 |
| 15. Drawing - Plan and Section
drawn based on information in
the project records | dated 30 June 1978 |

(1923)

Ashuelot Gas & Electric Co. Owners
L. H. Shattuck Inc. Contractors
Marlboro, N. H.
Minnewawa Brook

Started July 1923. Completed December 1923.
Plans were filed June 19, 1923.

Permission given to go ahead with construction July 6,
1923.

The excavation was started the first part of July.
Ledge was found the entire length of the dam. Pouring concrete
was started August 13, 1923 and the last pouring made November 12,
1923.

This is of solid concrete construction single arch type
60' high and 200' long. Drainage area is 22 sq. miles. The water
is taken by penstock downstream about six thousand feet to the Power
House, which gives them a head of 254'. The installation of this
plant is 2500 H.P.

Informal 1373 Plan D-49

157.06

INSTRUCTION
INSTRUCTION
IONS
IS

L. H. SHATTUCK, INC.
ENGINEERS-CONTRACTORS
208 GRANITE STREET
MANCHESTER, N. H.

REPORTS AND DESIGN
WATER POWER
WATER SUPPLY
SEWERAGE
BRIDGES

June 18, 1923.

RECEIVED

JUN 19 1923

N. H. Public Service Commission

Mr. John W. Storrs,
Chairman and Engineer,
New Hampshire Public Service Commission,
Concord, New Hampshire.

Subject: Dam to erected at
Marlboro, N. H., for Ashmelot
Gas & Electric Company, Keene, N.H.

Dear Sir:-

We are submitting plans and information in re-
gard to the design of the proposed dam for the Ashmelot Gas &
Electric Company at Marlboro, New Hampshire.

GENERAL DATA

The proposed dam will be built on Minnewawa Brook about
one and one-half miles above the village of Marlboro, N. H.
The watershed drained is 22 square miles. This watershed
while hilly contains several large ponds providing a consider-
able storage and tending to reduce the size of flood flows.

The maximum recorded spring floods from this and adjoin-
ing watersheds yield not over 25 cu. ft. per second per square
mile. In the design of the proposed dam we have anticipated a
maximum flood of 65 cu. ft. per second per square mile. The
design adopted would also permit an unexpected flood to flow
over the entire length of the dam without damage to the con-
struction.

Mr. John W. Storrs

-2-

5/18/23

The capacity of the proposed pond is about 140 acre feet or 600,000 cubic feet.

DESIGN DATA

As shown by the accompanying plans the proposed structure is a concrete arch dam of solid concrete masonry. The maximum height above river bed would be about 55 ft., and above foundations probably 60 ft. The thickness at the top is four feet and at the bottom eleven feet.

The dam is provided at its northern end with a spillway 40 ft. long and 5 ft. deep with a short auxiliary spillway 3 ft. deep. The capacity of this spillway to the top of the arch portion of the dam is about 1700 cu. ft. per second.

The dam will have a constant radius of 85 ft. to the upstream face.

The concrete used will be mixed in proportion one part cement, two ~~and one-half~~ ^{four (P.A.S.)} parts sand, ~~two~~ parts crushed stone or gravel and possibly an addition of cobbles or plums, if such an addition is found economical. To the concrete will be added eight parts of hydrated lime to one hundred parts by weight of cement to increase water tightness.

Mr. John W. Storrs

-3-

6/18/23.

COMPUTATION FOR DESIGN

Constant Radius Dam

Formula used

$$p = \frac{q r_u}{t} \quad \text{Creager page 149}$$

or

$$t = \frac{q r_u}{p}$$

p = Unit stress in concrete per square foot. Taken as 40,000# per square foot or 278# per square inch.

q = Load per square foot taken by the arch at any elevation.

t = Thickness of the arch in feet at any elevation.

r_u = Upstream radius of dam in feet. In this case = 85 ft.

RESULTS OF CALCULATIONS

Height h	Pressure $q = 62.5h$	Computed Thickness t	Thickness Used	Actual Unit Compression p
0	0	0	4	0+
10	625	1.33	4	13300
20	1250	2.66	5.5	19300
30	1875	4.00	7.0	22800
40	2500	5.32	7.5	28400
50	3125	6.65	10.0	26600
60	3750	8.00	11.0	29000

Taking the ultimate strength of 1-2½-5 concrete as 300,000# per sq. ft. we have a minimum factor of safety of over 10.

+Except from possible ice action.

-4-

CONSTRUCTION DATA

The site is a deep gorge in which the bed rock is only slightly overlaid with soil. The rock is a mica shist of varying hardness. In most cases where the ledge has been exposed the rock is hard, but on the south slope the dip of the strata is with the slope of the hill and the surface rock has been softened and loosened by frost and root action.

All of the partially disintegrated rock will be removed and a trench excavated in the hard rock. The foundation of the dam will be built in this trench. Preparation will be made to grout the seams in the rock if they are found to be loose on inspection and test drilling.

The horizontal joints in the dam will be as few as is practical and will be carefully cleaned and bonded. Vertical expansion joints will be spaced on about 40 ft. centers, and will be made water tight by the insertion of strips of sheet lead.

Plans The details of the proposed dam are shown on the accompanying plans.

We shall be glad to furnish the Commission with any additional information desired, or will accompany them when inspecting the site. We have attached a list of references used in the design of this structure, and a diagram of the maximum recorded flood flows on small New Hampshire streams.

Very truly yours,
L. H. SHATTUCK, INC.

REFERENCES USED IN DESIGN AND SPECIFICATION FOR ARCH DAM

1st & Principally

W. P. Creager - Masonry Dams, pages 148-171

2nd

Lamar Lyndon - Hydro-electric Power, Vol. I,
Pages 228-233

3rd

Concrete Engineers Handbook by Hool & Johnson, page 736

4th

Daughterty - Hydraulics, page 35

5th

American Society Civil Engineers proceedings -
April 1914 and discussions -
The Huacal Dam, Senora, Mexico. Describes and
illustrates a typical thin arch dam, with inter-
esting discussions of the design of arch dams.

6th

May 1914 and discussions -
The Constant Angle Arch Dam by Lars R. Jorgensen,
with discussion of the design of arch dams in
general.

151.06

1914 Van & B. Co. Minnerama Rock Dam

June-25-1923

$1020 = 85'$

$1020 - 1020 = 53'$

$1020 = 10'3\frac{1}{4}" = 10.25'$

$S = 62.3 \text{ RH}$

$15 = \frac{62.5 \times 85 \times 53}{10.25} = 27470. \square'$

$1020 = 85'$
 $1020 = 10'3\frac{1}{4}"$
 $1020 = 10.25'$

6.7958800

1.9294184

1.7242759

5.4495748

1.0107239

Log - 4.4388509

1.44" 2.158 3625

Log 2.2804984

$S = 19276 \frac{1}{4}"$


1.44" 2.158 3625

4.4388509

151.06

6

2




K. J. Johnson

ESTIMATED COMPLETED

ESTIMATED COMPLETED
ESTIMATED COMPLETED
ESTIMATED COMPLETED

RTM EXC.
ICK EXC.
ICREYED

ORIGINAL SURFACE
EXCAVATED MIDGE SURFA



Mr. L. W. Bigelow.

Oct. 4, 1923

DAM AT MARLBORO , ASUELOT GAS & ELECTRIC CO.

The following are the stations of the expansion joints

1+ 06.1 Gravity to arch
1+ 44.3
1+ 82.4
2+ 20.5
2+ 58.6

The following are the horizontal joint elevations.

1023.0 Top of footing.
1030.1
1036.3
1042.6
1048.8
1055.1
1061.3
1067.6
1073.0

The station of the sluice pipe is 1+ 84.6

157.06

L. H. SHATTUCK, INC.**ENGINEERS - CONTRACTORS****208 GRANITE STREET****MANCHESTER, N. H.**

REPORTS AND DESIGN

WATER POWER

WATER SUPPLY

SEWERAGE

BRIDGES

Marlboro, N.H.
October, 4, 1923

r. L. W. Bigelow,
/o Public Service Commission,
Concord, N. H.

Re., - Dam at Marlboro for Ashuelot Gas & Electric Co.

Dear Mr. Bigelow, -

In accordance with our conversation today I am sending you a sketch showing the profile of the dam, and the concrete poured to date. This profile does not include the spillway as we have taken no profile here yet. I will show this in a future letter to you after I have this information.

On another sheet enclosed I am giving the exact values of the elevations poured to each time, also the stationing of the expansion joints. The stationing is simply started by adopting a large enough value for the station of the sluice pipe to give us a positive value for all points on the dam. It is not started at any particular point. The profile is run on a line four feet back from the upstream side of the dam. The profile is drawn looking upstream.

Any other data which I can give you, I shall be pleased to do so at your request.

Very truly yours,

Richard J. Holmgren
Resident Engineer.

Inc.

D. WORTHEN
TORRES
COMMISSIONERS

OF
NEW HAMPSHIRE

WALTER H. HARRIS, CLERK
MISS MARY A. NAWN
ASSISTANT CLERK

CONCORD

September 19, 1923.

Public Service Commission,
Concord, New Hampshire.

Dear Sirs:

Herewith I submit my report on the inspection
of the dam at Marlboro for the Keene Gas & Electric Company.

The opening which was left for flow, as by my
report of September 7 has been closed. The flow is being
discharged now through the sluice gate. At the time I
was there it was running about one-third full.

The south half of the dam has been poured up
to elevation 1036. The north half would be up to elevation
1042 last night as they were pouring the section nearest
the bank while I was there. They expect, this week, to have
the concrete up to elevation 1042 the entire length of the
dam.

The power house is poured up to the roof and they
expect to have it roofed in the latter part of next week.

The work at the dam is being carried on in a
very satisfactory manner, all joints, both horizontal and
vertical, being kept free from chips and other dirt.

Respectfully submitted,



Engineer.

TESTING LABORATORY
REPORT ON SAMPLE OF PORTLAND CEMENT

Report 9/13 1923
Exam. 8/16 1923
Story No. 5870
Portland Cement Town
Location Marks
Made by L. E. Shattuck Co. Keepe Gas & Electric Co., Storrs, Bigelow
Title Address
Made 8/15, 1923 Received 8/15, 1923
From
Type represented
Kind of Material
Used or to be used
Made for

TEST RESULTS

CHEMICAL TESTS

Requirements: American Society for
Testing Materials and New Hampshire
Highway Department.

	Per cent.
Ignition, per cent.	not over 4.00
Insoluble residue, per cent.	not over 0.85
Sulfuric Anhydride (SO ₃), per cent.	not over 2.00
Magnesia (MgO), per cent.	not over 5.00

PHYSICAL TESTS

Specific Gravity not less than 3.10
Weight retained on 200 mesh sieve 18.7 not over 22.00
Test O.K. No distortion, cracking, checking or disintegration

GILLMORE NEEDLE

Set 2 hours 30 minutes not less than 60 minutes
Set 4 hours 5 minutes not over 10 hours

TENSILE STRENGTH
(1.3 Ottawa Sand.)

7 days.	28 days.
<u>321</u>	<u>303</u>
<u>321</u>	<u>391</u>
<u>309</u>	<u>426</u>
<u>307</u>	<u>400</u>
200 pounds	300 pounds

Average: 400

Meets requirements 7 & 28 day tests.

Respectfully submitted,

William E. Parsonette
Chemist and Testing Engineer.

HIGHWAY DEPARTMENT

TESTING LABORATORY

REPORT ON SAMPLE OF GRAVEL, SAND OR BITUMINOUS CONCRETE

Laboratory No. **3586** Report **9/20** 19**23**
 Exam. **8/20** 19**23**
 Name **Fine Aggregate for Concrete** Town **Keene**
 Identification Marks
L.L. Shattuck Co.-Keene Gas & Electric Co.-Stores-Bigelow
 Submitted by Title Address
 Sampled **8/17**, 19**23** Received **8/18**, 19**23**
 Sample from **Car from Garmon's Pit-B. wears, N.H.**
 Quantity represented
 Source of Material
 Location used or to be used **Keene Dam**
 Examined for

TEST RESULTS

SAND—Mechanical Analysis

FRACTION	%
Retained $\frac{1}{4}$ " screen	
Passing $\frac{1}{4}$ ", retained 10 mesh	
10, " 20 "	
20, " 30 "	
30, " 40 "	
40, " 50 "	
50, " 60 "	
60, " 80 "	
80, " 100 "	
100, " 200 "	
200, mesh	

GRAVEL—Mechanical Analysis

FRACTION	%
Retained $3\frac{1}{2}$ " screen	
Passing $3\frac{1}{2}$ ", retained 3"	
" 3" " $2\frac{1}{2}$ "	
" $2\frac{1}{2}$ " " 2"	
" 2" " $1\frac{1}{2}$ "	
" $1\frac{1}{2}$ " " 1"	
" 1" " $\frac{3}{4}$ "	
" $\frac{3}{4}$ " " $\frac{1}{2}$ "	
" $\frac{1}{2}$ " " $\frac{1}{4}$ "	
" $\frac{1}{4}$ " screen	
Fineness Modulus Coarser than #100—97 48—87 28—57 14—23 8—7 4—1 F.M.—2.74	
Total:	

Notes:

2
 COMPRESSIVE TENSILE STRENGTH (Cement-Sand Briquets—1:3)

SAMPLE SAND			STANDARD OTTAWA SAND		
3 day	7 day	28 day	3 day	7 day	28 day
	955	1564		924	1496
	1000	1701		856	1591
	1073	1615		901	1564
	1009	1627		894	1551
	1182	1945			

Per cent. of Wear.....

Asphalt%

Remarks:

Meets requirements #1 Sand on 7 &
 28 day tests. This sample is clean.

Chemist and Testing Engineer.

PUBLIC SERVICE COMMISSION

10/1/23

LEAH T. SUNNISON, CHAIRMAN
GEORGE W. D. WORTHEN
J. W. STORRS
COMMISSIONERS

OF

WALTER H. TIMM, CLERK
MISS MARY A. NAWN
ASSISTANT CLERK

NEW HAMPSHIRE

CONCORD

September 7, 1923.

Public Service Commission,
Concord, New Hampshire.

Dear Sirs:

I herewith submit a report on the inspection of the dam at Marlboro for the Keene Gas & Electric Company yesterday.

The concrete is poured up to elevation 1030, the full length, with the exception of an opening about eight feet in width which was left for the flow of water.

On the south end of the dam they were obliged to go down about 15' from approximately elevation 1020 to find a solid foundation owing to seams. Good solid rock was found at about elevation 1010 but they went about five feet in good solid rock. This pocket was only about 10' in length.

The cut-off on both banks has been carried down to good hard rock. In carrying the dam up, the cut-off will be filled solid with concrete on the upstream side as, of course, the line of ledge excavation is rather irregular.

The sluice gate was put in position yesterday and they expect to fill in the opening on Saturday and Sunday and send the water down through the sluice gate.

Construction seems to be carried on in a very workmanlike manner. The joints are kept free from dirt and debris.

They are using sectional forms which are very rigid and are handled by an overhead cableway. The forms are, also, kept clean and in good shape.

With ordinary working conditions they expect to finish the dam about the first or second week in October.

Respectfully submitted,

W. B. [Signature]
Engineer.

DATA ON DAMS IN NEW HAMPSHIRE

LOCATION

STATE NO. 151.06

Town Marlboro : County Cheshire

Stream Minnewawa Brook

Basin-Primary Connecticut R : Secondary Ashuelot R

Local Name

Coordinates—Lat. 42° 25' 1" 300' : Long. 72° 10' 1" 3550'

GENERAL DATA

Drainage area: Controlled 25 Sq. Mi.: Uncontrolled Sq. Mi.: Total 25 Sq. Mi.

Overall length of dam 250 ft.: Date of Construction

Height: Stream bed to highest elev. 30 ft.: Max. Structure 55 ft.

Cost—Dam : Reservoir

DESCRIPTION

Arch— Concrete on Ledge

Waste Gates

Type 1

Number : Size ft. high x ft. wide

Elevation Invert : Total Area sq. ft.

Hoist

Waste Gates Conduit

Number : Materials

Size ft.: Length ft.: Area sq. ft.

Embankment

Type

Height—Max. ft.: Min. ft.

Top—Width : Elev. ft.

Slopes—Upstream on : Downstream on

Length—Right of Spillway : Left of Spillway

Spillway

Materials of Construction

Length—Total 3 bays 14' each ft.: Net 42 ft.

Height of permanent section—Max. ft.: Min. ft.

Flashboards—Type : Height 2 ft.

Elevation—Permanent Crest 1072.228 : Top of Flashboard

Flood Capacity 1775 cfs.: 71 cfs/sq. mi.

Abutments

Materials:

Freeboard: Max. 5 ft.: Min. ft.

Headworks to Power Devel.—(See "Data on Power Development")

OWNER Public Service Co of N H

REMARKS

300 ft penstock— 4' in diameter

Tabulation By A. A. E. Date January 30, 1939

B&P21281

DATA ON RESERVOIRS & PONDS IN NEW HAMPSHIRE

LOCATION

AT DAM NO. 151.06

Town Marlboro : County Cheshire

Stream Minnewana Brook

Basin—Primary Connecticut : Secondary Ashuelot

Local Name

DRAINAGE AREA

Controlled 25 Sq. Mi.: Uncontrolled : Total : Sq. Mi.

ELEVATION vs. WATER SURFACE AREA vs. VOLUME

Point	Head Feet	Surface Area Acres	Volume Acre Ft.
(1) Max. Flood Height			
(2) Top of Flashboards			
(3) Permanent Crest			
(4) Normal Drawdown		140	
(5) Max. Drawdown			
(6) Original Pond			

Base Used : Coef. to change to U.S.G.S. Base

RESERVOIR CAPACITY

	Total Volume	Useable Volume
Drawdown	ft.	ft.
Volume	ac. ft.	ac. ft.
Acre ft. per sq. mi.		
Inches per sq. mi.		

USE OF WATER Public Utility

OWNER Public Service Co of N.H.

REMARKS

Tabulation By A.M. Date January 30, 1939

LOCATION

AT DAM NO.151.06.....

Town Marlboro : County Cheshire
Stream Minnewawa
Basin-Primary Connecticut : Secondary Ashuelot
Local Name

GENERAL DATA

Head-Max.289..... ft.: Min. ft.: Ave. ft.
Date of Construction : Use of Power ..Public..Utility.....
Pondage ac. ft.: Storage ac. ft.

DESCRIPTION

Racks

Size of Rack Opening
Size of Bar : Material
Area: Gross Sq. Ft.: Net sq. ft.

Head Gates

Type
Number : Size ft. high x ft. wide
Elevation of Invert : Total Area sq. ft.
Hoist

Penstock

Number1..... : MaterialWood.....
Size4' diameter..... : Length300'.....

Turbines

Number2..... : MakersS. Morgan Smith horizontal.....
Rating HP. per unit1250..... : Total Capacity2500..... HP.
Max. Dement C.F.S., per unit : Total cfs.

Drive

Type

Generator

Number2.....
MakeG. E.....
Rating KW., per unit800..... ; Total Capacity1600..... K. W.

Exciter

Number : Make
Rating-per unit : Total Capacity K. W.

OUTPUT--KWHRS

19.....	:	19.....
19.....	:	19.....
19.....	:	19.....
19.....	:	19.....
19.....	:	19.....

OWNER Public Service Co. of N. H.

Tabulation By Date January 22, 1939.....

Elv	Thickness Inches	Actual Unit of Compression	Unit of Comp. per Sq. In
1063.0	4.0	15781	109.59
1060.0	4.44	15355	108.02
1050.0	5.9	20710	143.82
1040.0	7.35	23852	165.64
1030.0	9.91	25929	130.00
1020.0	10.27	27611	191.74

Calculated Aug 23, 1923

These check Calculations submitted by
L.H. Shattuck Inc.

By *M. B. Lawrence*

157.06

$$S = 62.5 \times 85 \times 10$$

$$S = 15781$$

109.59

$$\begin{array}{r} 850 \\ 62.5 \\ \hline 4250 \\ 1700 \\ \hline 5100 \\ 4 \overline{) 50125.0} \\ \underline{15781.} \end{array}$$

$$\begin{array}{r} 171.74 \\ 122 \overline{) 27611} \\ \underline{144} \\ 1321 \\ \underline{1226} \\ 251 \\ \underline{144} \\ 1073 \\ \underline{1028} \\ 520 \\ \underline{576} \end{array}$$

$$\begin{array}{r} 150 \\ 144 \overline{) 25929} \\ \underline{144} \\ 1152 \\ \underline{1152} \end{array}$$

$$\begin{array}{r} 251 \\ 144 \\ \hline 1073 \\ 1028 \\ \hline 520 \\ 576 \end{array}$$

$$\begin{array}{r} 165.64 \\ 122 \overline{) 20252} \\ \underline{122} \\ 943 \\ \underline{943} \end{array}$$

109.59

$$122 \overline{) 25911}$$

$$\begin{array}{r} 122 \\ \hline 631 \\ \underline{576} \end{array}$$

$$\begin{array}{r} 550 \\ \underline{132} \end{array}$$

$$\begin{array}{r} 1180 \\ \underline{1152} \end{array}$$

280

$$\begin{array}{r} 122 \overline{) 15781} \\ \underline{122} \\ 3581 \\ \underline{358} \\ 576 \end{array}$$

$$\begin{array}{r} 1381 \\ \underline{1296} \\ 850 \\ \underline{720} \end{array}$$

$$144 \overline{) 13335} (103.02$$

$$\begin{array}{r} 1155 \\ \underline{1152} \end{array}$$

$$\begin{array}{r} 500 \\ \underline{288} \\ 12 \end{array}$$

radius of circle $S = 62.5 \frac{H.H}{T}$ (Williams P228) 157.06
 = head of water at point
 thickness of Dam

Formula $S = 62.5 \times 85 \times 53$

10.27	35	10.27
	53	3.81
	255	7.35
$S = 27611$	425	5.9
191.74	4505	4.44
	62.5	
	42535	
	9010	
	27030	
	283562.5	

$S = 62.5 \times 85 \times 43$

8.81	85	11.05
	43	10.27
$S = 25929$	255	7800
130.3	340	25929
	3655	
	62.5	
	15275	
	1310	
	21930	
	228437.5	

$S = 62.5 \times 85 \times 33$

7.35	85	23.85
	33	17.62
$S = 23352$	255	8230
105.64	255	7929
	62.5	
	14025	
	5610	
	16930	
	175312.5	

$S = 62.5 \times 85 \times 23$


5.9	85	38.23
	23	36.75
$S = 20710$	235	1500
143.32	170	
	1755	
	62.5	
	2575	
	3910	
	11730	
	122187.5	

$S = 62.5 \times 85 \times 13$

4.44	85	4.44
	13	
$S = 15555$	255	
105.64	1105	
	105	
	255	
	1105	
	1105	
	5405.5	

MANUEL TO DEVELOPMENT,
CROSS SECTION OF DAM
POURING BEHIND EXCAVATION AND CONCRETE POURINGS
TO DATE OCTOBER 27, 1953

FOR OFFICE
MANCHESTER, N.H.
CHIEF ENGINEER




P. H. Holmgren
RESIDENT ENGINEER

IGN

L. H. SHATTUCK, INC.

157.06

157.06



11-0-0-0

0700

1060

1040

1020

1000

OF
NEW HAMPSHIRE

INSPECTOR'S REPORT

November 6 19 23

Subject: Dam, Marlboro; Ashuelot Light & Power Co.

Herewith I submit my report on the inspection of the dam at Marlboro for The Ashuelot Light & Power Company on Nov. 5th.


The abutment section of the dam has been completed from station 1 + 00 to about station 2 + 63. From 2 + 63 to the south end the concrete has been poured to Elv. 261.0, and this should be completed by the end of this week.

On the spillway excavation they run into a pocket and the ^{ON} yamage was increased quite a lot from the original estimate but this has been completed and they will start pouring concrete this week.

The power house is completed with the exception of the doors and windows.

About two thousand feet of the penstock line is in place most of which is on the power house end. They have now started in and are laying from the dam as well.

Respectfully submitted,



Engineer.

Attached is progress chart to Nov. 5th.

OF
NEW HAMPSHIRE

INSPECTOR'S REPORT

December 4, 1923.

Subject: Dam, Marlboro; Ashuelot Gas & Electric Co.

I herewith submit my report for the final inspection of the dam at Marlboro for the Ashuelot Gas & Electric Company on December 4th.

The concrete has all been placed in both the abutment and spillway sections of the dam. The racks and gate for penstock are all in place. Railings have also been placed along the crest of the abutment section, and a wooden bridge has been built from the tank accrossed the spillway to the end of the abutment section.

At the time of my inspection there was about a foot of water going over the spillway which made the water in the earth pond at about elevation 1069. The which was not excavated below the spillway has been washed out by the high water of Nov. 24th when the water reached an elevation of 1070, this has left the ledge exposed the entire length the spillway from the concrete to top of the cliff. This shows up a natural channel in the ledge.

There is a slight seepage through the concrete at about elevation 1040 at about station 1+70 and covers about six sq. ft. but does not amount to anything more than a slight moisture on the surface.

PUBLIC SERVICE COMMISSION
OF
NEW HAMPSHIRE

157.06

INSPECTOR'S REPORT

19

Subject: Dam, Marlboro continued

The penstock has been completed to within about thirty feet of the Power House. The surge tank is about 50% erected.

At the Power House the Transformer tower is about 75% complete.

The Company expects under fair working conditions to have the power house in operation sometime in January.

The work has been carried on throughout in a business and workmanlike manner.

Respectfully submitted,

J. W. G. Jones

Engineer.

Marlboro
Page 4

151.00
Inspected June 19, 1930.

Public Service Company of N. H.

Minnewawa Dam.

Concrete arch dam. The spillway has splashboards at present. Considerable brush and timber collected at spillway. The downstream face of the dam shows evidence of small seepage, and several panels have surface filling similar to that shown at intake. The bed of the stream below the dam was fairly dry. There is one stone arch small dam above the power station and two small timber dams in ruins. These are all former dams owned by the Keene Gas and Electric Company in Marlboro. The small stone arch dam is in good shape.

DIVI-16

DIVI-17

DIVI-18

M E M O

August 27, 1976

Dam #151.06


On August 3rd I inspected the dam on the Minnewawa Brook.

This dam has no structural changes since the last inspection
(November 1974).

There are some rebars showing on the upstream face.

This dam should be inspected in two years.

SCBurritt



APPENDIX C

PHOTOGRAPHS

- | | |
|--------|---|
| Fig. 1 | Facing Upstream from Dam |
| Fig. 2 | Facing Downstream from Dam |
| Fig. 3 | Right Abutment (downstream face) |
| Fig. 4 | Left Abutment (downstream face) |
| Fig. 5 | Downstream Face (Note surface cracks and efflorescence) |
| Fig. 6 | Downstream Face |
| Fig. 7 | Walkway at Top of Dam El. 1073 |
| Fig. 8 | Upstream Face |
| Fig. 9 | Intake Structure for Penstock, trash racks (Note excessive buildup of debris) |
| Fig.10 | Detailed View of Condition of concrete on upstream face |
| Fig.11 | Gate - Operating Machinery at Inlet to Penstock and Cabinet for water level Indicator |
| Fig.12 | Work platform at inlet structure |
| Fig.13 | Outlet - 24" dia. Sluice & 48" dia. Penstock |
| Fig.14 | Outlet - 48" dia. Penstock |
| Fig.15 | Outlet - 24" dia. Sluice and Gate Valve |
| Fig.16 | Upstream View of Spillway |
| Fig.17 | Spillway Outlet Channel thru V-Notch in ledge |
| Fig.18 | Facing Upstream from Dam |
| Fig.19 | Upstream Face of Arch (Note exposed reinforcing steel) |
| Fig.20 | Inlet Structure |
| Fig.21 | Detail of Exposed Reinforcing Steel and Spalled Concrete Surfaces |

Fig.22	Gate-Operating Machinery
Fig.23	Detail of Inlet Structure Wall
Fig.24	Trash Rack
Fig.25	Detail of Exposed Steel and Debris at Inlet
Fig.26	Spillway
Fig.27	Upstream Intake for 24" Dia. Sluice




PHOTO INDEX

MINNEAPOLIS DAM



FIG. 1 Facing Upstream from Dam



FIG. 2 Facing Downstream from Dam

WHEREAS WATERWAY
IN OVERFLOW COMPS.

BY L. M. M. M. CHECKED BY Spr. E. M. M. S. C. DATE 1/15

1 E. M. M.

(1.25)

$$C = 3.4$$

$$L = 43.5$$

$$CL = 147.9$$

1.25	$Q = 0$
1.50	$Q = 147.9(.5)^{3.4} = 52.4$ <i>ofs</i>
1.69	$Q = 147.9(1)^{3.4} = 148$
2.00	$Q = 147.9(2)^{3.4} = 419$
2.71	$Q = 147.9(3)^{3.4} = 769$
2.72	$Q = 147.9(4)^{3.4} = 1183$
3.00	$Q = 147.9(5)^{3.4} = 1653$
3.73.5	$Q = 147.9(5.5)^{3.4} = 1908$
4.14	$Q = 147.9(6)^{3.4} = 2173$
4.15	$Q = 147.9(7)^{3.4} = 2739$
4.17	$Q = 147.9(9)^{3.4} = 3993$
4.20	$Q = 147.9(12)^{3.4} = 6148$
4.21	$Q = 147.9(15)^{3.4} = 6932$

ATION

ED BY

CHECKED BY

DATE

Billway Cr.

K687

Dam Cr. 1073

22'

A = 12.56 ft²

4'

penstock

52'

$$Q = CA\sqrt{2gh}$$

C = .58

2g = 64.4

A = 3.14 ft²

El. 102.0

12'

Sluice

SLUICE

WS. @ 1068 (SP. 11)

PENSTOCK

$$= .58(3.14)\sqrt{64.4(47)}$$

$$Q = 100 \text{ cfs}$$

$$= .58(3.14)\sqrt{64.4(52)}$$

$$Q = 105 \text{ cfs}$$

$$= .58(3.14)\sqrt{64.4(5)}$$

$$Q = 112 \text{ cfs}$$

$$Q_T = 341$$

WS @ 1074

$$Q_T = 379$$

WS @ 1080

$$Q_T = 477$$

$$Q = .58(12.56)\sqrt{64.4 \times 17}$$


$$Q = 241 \text{ cfs}$$

$$Q = .58(12.56)\sqrt{64.4 \times 22}$$

$$Q = 274$$

$$Q = .58(12.56)\sqrt{64.4 \times 22}$$

$$Q = 274$$



APPENDIX D




FIG. 26 Spillway




FIG. 27 Upstream Intake for 24" Dia. Sluice



FIG. 24 Trash Rack



FIG. 25 Detail of Exposed Steel and Debris at Inlet



FIG. 22 Gate-Operating Machinery



FIG. 23 Detail of Inlet Structure Wall



FIG. 20 Inlet Structure



FIG. 21 Detail of Exposed Reinforcing Steel and Spalled Concrete Surfaces



FIG. 18 Facing Upstream from Dam




FIG. 19 Upstream Face of Arch (Note Exposed reinforcing steel)



FIG. 16 Upstream View of Spillway



FIG. 17 Spillway Outlet Channel
thru V-Notch in ledge.



FIG. 13 Outlet - 24" dia. Sluice &
Penstock



FIG. 14 Outlet - 48" dia. Penstock



FIG. 15 Outlet - 14" dia. Sluice and Gate Valve



FIG. 11 Gate - Operating Machinery at Inlet to Penstock
and Cabinet for water level Indicator




FIG. 12 Work platform at inlet structure



FIG. 8 Upstream Face



FIG. 9 Intake Structure for Penstock,
trash racks (Note excessive buildup
of debris)



FIG. 10 Detailed View of Condition
of concrete on upstream face




FIG. 6 Downstream Face




FIG. 7 Walkway At Top of Dam El. 1073

SUBJECT

COMPUTATION

COMPUTED BY

CHECKED BY

DATE

(ft, mcl)

Dem Sec

2 200
2 series

1143

1143

1143

$$Q = 2.6(200)(.5)^{3/2} = 184$$

1143

$$Q = 2.7(200)(1)^{3/2} = 540$$

1075

$$Q = 2.7(200)(2)^{3/2} = 1527$$

1143

$$Q = 2.8(200)(4)^{3/2} = 4480$$

1143

$$Q = 3.3(200)(7)^{3/2} = 12223$$

1143

$$Q = 3.3(200)(8)^{3/2} = 14934$$

TOTAL FLOW

TOTAL FLOW

1511

1143

0

1143

118

1143

118

1143

119

4119

1143

119

701

1143

1183

1183

1143

1653

1653

1143

1908

184

2092

1143

2173

540

2713

1143

2173

1527

4266

1143

2173

4480

8473

1143

6000

12223

18371


1143

1184

14934

21866

"RULE OF THUMB" GUIDANCE FOR ESTIMATING DOWNSTREAM DAM FAILURE HYDROGRAPHS



STEP 1: DETERMINE OR ESTIMATE RESERVOIR STORAGE (S) IN AC-FT AT TIME OF FAILURE.

STEP 2: DETERMINE PEAK FAILURE OUTFLOW (Q_{p1}).

$$Q_{p1} = \frac{8}{27} W_b \sqrt{g} Y_0^{3/2}$$

W_b = BREACH WIDTH - SUGGEST VALUE NOT GREATER THAN 40% OF DAM LENGTH ACROSS RIVER AT MID HEIGHT.

Y_0 = TOTAL HEIGHT FROM RIVER BED TO POOL LEVEL AT FAILURE.

STEP 3: USING USGS TOPO OR OTHER DATA, DEVELOP REPRESENTATIVE STAGE-DISCHARGE RATING FOR SELECTED DOWNSTREAM RIVER REACH.

STEP 4: ESTIMATE REACH OUTFLOW (Q_{p2}) USING FOLLOWING ITERATION.

A. APPLY Q_{p1} TO STAGE RATING, DETERMINE STAGE AND ACCOMPANYING VOLUME (V_1) IN REACH IN AC-FT. (NOTE: IF V_1 EXCEEDS $1/2$ OF S, SELECT SHORTER REACH.)

B. DETERMINE TRIAL Q_{p2} .

$$Q_{p2}(\text{TRIAL}) = Q_{p1} \left(1 - \frac{V_1}{S}\right)$$

C. COMPUTE V_2 USING Q_{p2} (TRIAL).

D. AVERAGE V_1 AND V_2 AND COMPUTE Q_{p2} .

$$Q_{p2} = Q_{p1} \left(1 - \frac{V_{\text{avg}}}{S}\right)$$


STEP 5: FOR SUCCEEDING REACHES, REPEAT STEPS 3 AND 4.

APRIL 1978

Minecreek Brook
 Stage/discharge rating of typical channel section
 heraway

CHECKED BY

DATE 6/78



$$Q = \frac{1.49}{n} AR^{2/3} S^{1/2}$$

assume $n = .065$

$$S = .202$$

$$Q = 4.63 AR^{2/3}$$

$$AR^{2/3} = \frac{Q}{4.63}$$

Substituting ave. depth (D) for R:

$$AD^{2/3} = \frac{Q}{4.63}$$

$$Q = 4.63 AD^{2/3}$$

SUBJECT

Muskegon Channel Rating


COMPUTATION

Loraway


CHECKED BY

DATE

COMPUTED BY



Res. Elev. in Feet, msl



Storage, acre-feet

PUBLIC SERVICE CO. OF N.H.
DAM ON
MINNEWANA BROOK -
MARLBORO, N.H.
CAPACITY CURVE
JAN., 1978

APPENDIX E
INFORMATION AS CONTAINED IN
THE NATIONAL INVENTORY OF DAMS

END

FILMED

7-85

DTIC